

## Hex Head Cap Screws

### STAINLESS STEEL

- 18-8 Stainless steel for superior corrosion resistance
- Rockwell Hardness B87 - B98
- Meets or exceeds ASME/ANSI B18.2.1 and ASTM F788
- Lot controlled for full traceability

### GRADE 2

- Zinc chromate plated — Low Carbon Steel
- Meets or exceeds ANSI/ASME B18.2.1, SAE J429, SAE J1061 and ASTM 788 Standards
- Use with finished hex nut

### GRADE 5 COARSE THREAD

- Zinc chromate plated medium carbon steel quenched and tempered
- Lot controlled for full traceability
- Meets or exceeds ANSI/ASME B18.2.1, SAE J1061, SAE J429/ASTM A449 specifications for tensile strength and hardness
- Use Grade 5 Hex Nut with Grade 5 bolt

### GRADE 8

- Zinc and gold dichromate plated
- Medium carbon alloy steel quenched and tempered
- Lot controlled for full traceability
- Meets or exceeds ANSI/ASME B18.2.1, J429, J1061, and ASTM/788 standards
- Use Grade 8 Hex Nuts with Grade 8 bolt




Cap Screw Diameter Inches (mm)	W Width of Hex Head Inches (mm)	H Height Inches (mm)	TL Thread Length Inches (mm)
1/4 (6.35)	7/16 (11.11)	5/32 (3.97)	0.750 (19.05)
5/16 (7.94)	1/2 (25.40)	13/64 (5.16)	0.875 (22.23)
3/8 (9.53)	9/16 (14.29)	15/64 (5.95)	1.000 (25.40)
7/16 (11.11)	5/8 (15.88)	9/32 (7.14)	1.125 (28.58)
1/2 (12.70)	3/4 (19.05)	5/16 (7.94)	1.250 (31.75)
9/16 (14.29)	13/16 (20.64)	23/64 (9.13)	1.375 (34.93)
5/8 (15.88)	15/16 (23.81)	25/64 (9.92)	1.500 (38.10)
3/4 (19.05)	1 1/8 (28.58)	15/32 (11.91)	1.750 (44.45)
7/8 (22.26)	1 5/16 (33.34)	35/64 (13.89)	2.000 (50.80)
1 (25.40)	1 1/2 (38.10)	39/64 (15.48)	2.250 (57.15)

Grade Marking	Specification	Material	Nominal Size (Inches)	Proof Load (psi)	Tensile Strength (psi)	Core Hardness Min. Max.	Surface Hardness Max.
	SAE-Grade 2	Low Carbon Steel	1/4 through 3/4 over 3/4 through 1 1/2	55,000 33,000	74,000 60,000	B80 B100 B70 B100	— —
	SAE-Grade 5	Med. Carbon Steel Quenched and Tempered	1/4 through 1 over 1 through 1 1/2	85,000 74,000	120,000 105,000	C25 C34 C19 C30	30N54 30N50
	SAE-Grade 8	Med. Carbon Alloy Steel Quenched and Tempered	1/4 through 1 1/2	120,000	150,000	C33 C39	30N88.6
	18-8 (300 Series) Stainless Steel	Stainless Steel	1/4 through 1	—	90,000 125,000	B85 B95	—

To learn more about B-I-A please visit us at our  
**WEB site: [www.BiaGmbH.com](http://www.BiaGmbH.com)**




**CONTINUED**




Grade 2



Grade 5



Grade 8



Stainless Steel

Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)
----------	---------------------------------	----------	---------------------------------	----------	---------------------------------	----------	---------------------------------

## Hex Head Cap Screws 1/4"-20 - USS COARSE THREAD

100	G2 1/4-20 x 3/8	100	G5 1/4-20 x 3/8	—	—	100	SS 1/4-20 x 3/8
100	G2 1/4-20 x 1/2	100	G5 1/4-20 x 1/2	100	G8 1/4-20 x 1/2	100	SS 1/4-20 x 3/8
100	G2 1/4-20 x 5/8	100	G5 1/4-20 x 5/8	—	—	100	SS 1/4-20 x 5/8
100	G2 1/4-20 x 3/4	100	G5 1/4-20 x 3/4	100	G8 1/4-20 x 3/4	100	SS 1/4-20 x 3/4
100	G2 1/4-20 x 7/8	100	G5 1/4-20 x 7/8	—	—	—	—
100	G2 1/4-20 x 1	100	G5 1/4-20 x 1	100	G8 1/4-20 x 1	100	SS 1/4-20 x 1
100	G2 1/4-20 x 1-1/4	100	G5 1/4-20 x 1-1/4	100	G8 1/4-20 x 1-1/4	100	SS 1/4-20 x 1-1/4
100	G2 1/4-20 x 1-1/2	100	G5 1/4-20 x 1-1/2	100	G8 1/4-20 x 1-1/2	100	SS 1/4-20 x 1-1/2
100	G2 1/4-20 x 1-3/4	100	G5 1/4-20 x 1-3/4	100	G8 1/4-20 x 1-3/4	100	SS 1/4-20 x 1-3/4
100	G2 1/4-20 x 2	100	G5 1/4-20 x 2	100	G8 1/4-20 x 2	100	SS 1/4-20 x 2
100	G2 1/4-20 x 2-1/4	100	G5 1/4-20 x 2-1/4	100	G8 1/4-20 x 2-1/4	50	SS 1/4-20 x 2-1/4
100	G2 1/4-20 x 2-1/2	100	G5 1/4-20 x 2-1/2	100	G8 1/4-20 x 2-1/2	50	SS 1/4-20 x 2-1/2
100	G2 1/4-20 x 2-3/4	100	G5 1/4-20 x 2-3/4	100	G8 1/4-20 x 2-3/4	50	SS 1/4-20 x 2-3/4
100	G2 1/4-20 x 3	100	G5 1/4-20 x 3	100	G8 1/4-20 x 3	50	SS 1/4-20 x 3
—	—	100	G5 1/4-20 x 3-1/4	—	—	—	—
100	G2 1/4-20 x 3-1/2	100	G5 1/4-20 x 3-1/2	100	G8 1/4-20 x 3-1/2	50	SS 1/4-20 x 3-1/2
—	—	100	G5 1/4-20 x 3-3/4	—	—	—	—
100	G2 1/4-20 x 4	100	G5 1/4-20 x 4	100	G8 1/4-20 x 4	50	SS 1/4-20 x 4
—	—	100	G5 1/4-20 x 4-1/2	—	—	—	—
100	G2 1/4-20 x 5	100	G5 1/4-20 x 5	—	—	—	—
100	G2 1/4-20 x 5-1/2	100	G5 1/4-20 x 5-1/2	—	—	—	—
100	G2 1/4-20 x 6	100	G5 1/4-20 x 6	—	—	—	—
100	G2 1/4-20 x 6-1/2	—	—	—	—	—	—
100	G2 1/4-20 x 8	100	G5 1/4-20 x 8	—	—	—	—

## Hex Head Cap Screws 1/4"-28 - SAE FINE THREAD

—	—	100	G5 1/4-28 x 1/2	100	G8 1/4-28 x 1/2	—	—
—	—	100	G5 1/4-28 x 5/8	—	—	—	—
—	—	100	G5 1/4-28 x 3/4	100	G8 1/4-28 x 3/4	—	—
—	—	100	G5 1/4-28 x 1	100	G8 1/4-28 x 1	—	—
—	—	100	G5 1/4-28 x 1-1/4	—	—	—	—
—	—	100	G5 1/4-28 x 1-1/2	100	G8 1/4-28 x 1-1/2	—	—
—	—	100	G5 1/4-28 x 1-3/4	—	—	—	—
—	—	100	G5 1/4-28 x 2	100	G8 1/4-28 x 2	—	—
—	—	100	G5 1/4-28 x 2-1/2	—	—	—	—
—	—	100	G5 1/4-28 x 3	—	—	—	—
—	—	100	G5 1/4-28 x 5-1/2	—	—	—	—

## Hex Head Cap Screws 5/16"-18 - USS COARSE THREAD

100	G2 5/16-18 x 1/2	100	G5 5/16-18 x 1/2	100	G8 5/16-18 x 1/2	100	SS 5/16-18 x 1/2
100	G2 5/16-18 x 5/8	100	G5 5/16-18 x 5/8	—	—	100	SS 5/16-18 x 5/8
100	G2 5/16-18 x 3/4	100	G5 5/16-18 x 3/4	100	G8 5/16-18 x 3/4	100	SS 5/16-18 x 3/4
100	G2 5/16-18 x 7/8	100	G5 5/16-18 x 7/8	—	—	—	—
100	G2 5/16-18 x 1	100	G5 5/16-18 x 1	100	G8 5/16-18 x 1	100	SS 5/16-18 x 1
100	G2 5/16-18 x 1-1/4	100	G5 5/16-18 x 1-1/4	100	G8 5/16-18 x 1-1/4	100	SS 5/16-18 x 1-1/4
100	G2 5/16-18 x 1-1/2	100	G5 5/16-18 x 1-1/2	100	G8 5/16-18 x 1-1/2	100	SS 5/16-18 x 1-1/2
100	G2 5/16-18 x 1-3/4	100	G5 5/16-18 x 1-3/4	100	G8 5/16-18 x 1-3/4	100	SS 5/16-18 x 1-3/4
100	G2 5/16-18 x 2	100	G5 5/16-18 x 2	100	G8 5/16-18 x 2	100	SS 5/16-18 x 2
100	G2 5/16-18 x 2-1/4	100	G5 5/16-18 x 2-1/4	—	—	50	SS 5/16-18 x 2-1/4
100	G2 5/16-18 x 2-1/2	100	G5 5/16-18 x 2-1/2	100	G8 5/16-18 x 2-1/2	50	SS 5/16-18 x 2-1/2
100	G2 5/16-18 x 2-3/4	100	G5 5/16-18 x 2-3/4	100	G8 5/16-18 x 2-3/4	50	SS 5/16-18 x 2-3/4
100	G2 5/16-18 x 3	100	G5 5/16-18 x 3	100	G8 5/16-18 x 3	50	SS 5/16-18 x 3
—	—	50	G5 5/16-18 x 3-1/4	—	—	—	—
50	G2 5/16-18 x 3-1/2	50	G5 5/16-18 x 3-1/2	50	G8 5/16-18 x 3-1/2	50	SS 5/16-18 x 3-1/2
50	G2 5/16-18 x 4	50	G5 5/16-18 x 4	50	G8 5/16-18 x 4	50	SS 5/16-18 x 4
50	G2 5/16-18 x 4-1/2	50	G5 5/16-18 x 4-1/2	—	—	—	—
50	G2 5/16-18 x 5	50	G5 5/16-18 x 5	50	G8 5/16-18 x 5	—	—
50	G2 5/16-18 x 6	50	G5 5/16-18 x 6	—	—	—	—
50	G2 5/16-18 x 7	50	G5 5/16-18 x 7	—	—	—	—
50	G2 5/16-18 x 8	50	G5 5/16-18 x 8	—	—	—	—


CONTINUED




Grade 2



Grade 5



Grade 8



Stainless Steel

Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)
----------	---------------------------------	----------	---------------------------------	----------	---------------------------------	----------	---------------------------------

### Hex Head Cap Screws 5/16"-24 - SAE FINE THREAD

—	—	100	G5 5/16-24 x 1/2	—	—	—	—
—	—	100	G5 5/16-24 x 5/8	—	—	—	—
—	—	100	G5 5/16-24 x 3/4	100	G8 5/16-24 x 3/4	—	—
—	—	100	G5 5/16-24 x 1	100	G8 5/16-24 x 1	—	—
—	—	100	G5 5/16-24 x 1-1/4	100	G8 5/16-24 x 1-1/4	—	—
—	—	100	G5 5/16-24 x 1-1/2	100	G8 5/16-24 x 1-1/2	—	—
—	—	100	G5 5/16-24 x 1-3/4	—	—	—	—
—	—	100	G5 5/16-24 x 2	100	G8 5/16-24 x 2	—	—
—	—	100	G5 5/16-24 x 2-1/2	—	—	—	—
—	—	100	G5 5/16-24 x 3	—	—	—	—
—	—	50	G5 5/16-24 x 3-1/4	—	—	—	—
—	—	50	G5 5/16-24 x 5	—	—	—	—

### Hex Head Cap Screws 3/8"-16 - USS COARSE THREAD


100	G2 3/8-16 x 1/2	100	G5 3/8-16 x 1/2	100	G8 3/8-16 x 1/2	100	SS 3/8-16 x 1/2
100	G2 3/8-16 x 5/8	100	G5 3/8-16 x 5/8	—	—	—	—
100	G2 3/8-16 x 3/4	100	G5 3/8-16 x 3/4	100	G8 3/8-16 x 3/4	100	SS 3/8-16 x 3/4
—	—	100	G5 3/8-16 x 7/8	—	—	—	—
100	G2 3/8-16 x 1	100	G5 3/8-16 x 1	100	G8 3/8-16 x 1	100	SS 3/8-16 x 1
100	G2 3/8-16 x 1-1/4	100	G5 3/8-16 x 1-1/4	100	G8 3/8-16 x 1-1/4	100	SS 3/8-16 x 1-1/4
100	G2 3/8-16 x 1-1/2	100	G5 3/8-16 x 1-1/2	100	G8 3/8-16 x 1-1/2	100	SS 3/8-16 x 1-1/2
100	G2 3/8-16 x 1-3/4	100	G5 3/8-16 x 1-3/4	100	G8 3/8-16 x 1-3/4	100	SS 3/8-16 x 1-3/4
100	G2 3/8-16 x 2	100	G5 3/8-16 x 2	100	G8 3/8-16 x 2	100	SS 3/8-16 x 2
50	G2 3/8-16 x 2-1/4	50	G5 3/8-16 x 2-1/4	50	G8 3/8-16 x 2-1/4	50	SS 3/8-16 x 2-1/4
50	G2 3/8-16 x 2-1/2	50	G5 3/8-16 x 2-1/2	50	G8 3/8-16 x 2-1/2	50	SS 3/8-16 x 2-1/2
50	G2 3/8-16 x 2-3/4	50	G5 3/8-16 x 2-3/4	50	G8 3/8-16 x 2-3/4	50	SS 3/8-16 x 2-3/4
50	G2 3/8-16 x 3	50	G5 3/8-16 x 3	50	G8 3/8-16 x 3	50	SS 3/8-16 x 3
50	G2 3/8-16 x 3-1/4	50	G5 3/8-16 x 3-1/4	50	G8 3/8-16 x 3-1/4	—	—
50	G2 3/8-16 x 3-1/2	50	G5 3/8-16 x 3-1/2	50	G8 3/8-16 x 3-1/2	50	SS 3/8-16 x 3-1/2
—	—	50	G5 3/8-16 x 3-3/4	—	—	—	—
50	G2 3/8-16 x 4	50	G5 3/8-16 x 4	50	G8 3/8-16 x 4	50	SS 3/8-16 x 4
50	G2 3/8-16 x 4-1/2	50	G5 3/8-16 x 4-1/2	50	G8 3/8-16 x 4-1/2	50	SS 3/8-16 x 4-1/2
50	G2 3/8-16 x 5	50	G5 3/8-16 x 5	50	G8 3/8-16 x 5	50	SS 3/8-16 x 5
50	G2 3/8-16 x 5-1/2	50	G5 3/8-16 x 5-1/2	50	G8 3/8-16 x 5-1/2	—	—
50	G2 3/8-16 x 6	50	G5 3/8-16 x 6	50	G8 3/8-16 x 6	50	SS 3/8-16 x 6
50	G2 3/8-16 x 6-1/2	—	—	—	—	—	—
50	G2 3/8-16 x 7	—	—	—	—	—	—
50	G2 3/8-16 x 8	—	—	—	—	—	—
50	G2 3/8-16 x 9	—	—	—	—	—	—

### Hex Head Cap Screws 3/8"-24 - SAE FINE THREAD


—	—	100	G5 3/8-24 x 1/2	—	—	—	—
—	—	100	G5 3/8-24 x 3/4	—	—	—	—
—	—	100	G5 3/8-24 x 1	100	G8 3/8-24 x 1	—	—
—	—	100	G5 3/8-24 x 1-1/4	100	G8 3/8-24 x 1-1/4	—	—
—	—	100	G5 3/8-24 x 1-1/2	100	G8 3/8-24 x 1-1/2	—	—
—	—	100	G5 3/8-24 x 1-3/4	—	—	—	—
—	—	100	G5 3/8-24 x 2	100	G8 3/8-24 x 2	—	—
—	—	50	G5 3/8-24 x 2-1/2	50	G8 3/8-24 x 2-1/2	—	—
—	—	50	G5 3/8-24 x 3	50	G8 3/8-24 x 3	—	—
—	—	50	G5 3/8-24 x 5-1/2	—	—	—	—
—	—	—	—	50	G8 3/8-24 x 6	—	—



Grade 2



Grade 5



Grade 8



Stainless Steel

Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)
----------	---------------------------------	----------	---------------------------------	----------	---------------------------------	----------	---------------------------------

### Hex Head Cap Screws 7/16"-14 - USS COARSE THREAD

—	—	100	G5 7/16-14 x 3/4	100	G8 7/16-14 x 3/4	—	—
100	G2 7/16-14 x 1	100	G5 7/16-14 x 1	100	G8 7/16-14 x 1	—	—
50	G2 7/16-14 x 1-1/4	50	G5 7/16-14 x 1-1/4	50	G8 7/16-14 x 1-1/4	—	—
50	G2 7/16-14 x 1-1/2	50	G5 7/16-14 x 1-1/2	50	G8 7/16-14 x 1-1/2	—	—
50	G2 7/16-14 x 1-3/4	50	G5 7/16-14 x 1-3/4	50	G8 7/16-14 x 1-3/4	—	—
50	G2 7/16-14 x 2	50	G5 7/16-14 x 2	50	G8 7/16-14 x 2	—	—
—	—	50	G5 7/16-14 x 2-1/4	50	G8 7/16-14 x 2-1/4	—	—
50	G2 7/16-14 x 2-1/2	50	G5 7/16-14 x 2-1/2	50	G8 7/16-14 x 2-1/2	—	—
—	—	50	G5 7/16-14 x 2-3/4	—	—	—	—
50	G2 7/16-14 x 3	50	G5 7/16-14 x 3	50	G8 7/16-14 x 3	—	—
—	—	25	G5 7/16-14 x 3-1/2	25	G8 7/16-14 x 3-1/2	—	—
25	G2 7/16-14 x 4	25	G5 7/16-14 x 4	25	G8 7/16-14 x 4	—	—
—	—	25	G5 7/16-14 x 4-1/2	—	—	—	—
—	—	25	G5 7/16-14 x 5	—	—	—	—

### Hex Head Cap Screws 7/16"-20 - SAE FINE THREAD

—	—	100	G5 7/16-20 x 3/4	—	—	—	—
—	—	100	G5 7/16-20 x 1	—	—	—	—
—	—	50	G5 7/16-20 x 1-1/4	—	—	—	—
—	—	50	G5 7/16-20 x 1-1/2	50	G8 7/16-20 x 1-1/2	—	—
—	—	50	G5 7/16-20 x 1-3/4	—	—	—	—
—	—	50	G5 7/16-20 x 2	50	G8 7/16-20 x 2	—	—
—	—	50	G5 7/16-20 x 2-1/2	50	G8 7/16-20 x 2-1/2	—	—
—	—	50	G5 7/16-20 x 3	—	—	—	—
—	—	—	—	25	G8 7/16-20 x 3-1/2	—	—
—	—	—	—	25	G8 7/16-20 x 4	—	—

### Hex Head Cap Screws 1/2"-13 - USS COARSE THREAD

50	G2 1/2-13 x 3/4	50	G5 1/2-13 x 3/4	—	—	50	SS 1/2-13 x 3/4
—	—	50	G5 1/2-13 x 7/8	—	—	—	—
50	G2 1/2-13 x 1	50	G5 1/2-13 x 1	50	G8 1/2-13 x 1	50	SS 1/2-13 x 1
50	G2 1/2-13 x 1-1/4	50	G5 1/2-13 x 1-1/4	50	G8 1/2-13 x 1-1/4	50	SS 1/2-13 x 1-1/4
50	G2 1/2-13 x 1-1/2	50	G5 1/2-13 x 1-1/2	50	G8 1/2-13 x 1-1/2	50	SS 1/2-13 x 1-1/2
50	G2 1/2-13 x 1-3/4	50	G5 1/2-13 x 1-3/4	50	G8 1/2-13 x 1-3/4	50	SS 1/2-13 x 1-3/4
50	G2 1/2-13 x 2	50	G5 1/2-13 x 2	50	G8 1/2-13 x 2	50	SS 1/2-13 x 2
50	G2 1/2-13 x 2-1/4	50	G5 1/2-13 x 2-1/4	50	G8 1/2-13 x 2-1/4	50	SS 1/2-13 x 2-1/4
50	G2 1/2-13 x 2-1/2	50	G5 1/2-13 x 2-1/2	50	G8 1/2-13 x 2-1/2	50	SS 1/2-13 x 2-1/2
50	G2 1/2-13 x 2-3/4	50	G5 1/2-13 x 2-3/4	50	G8 1/2-13 x 2-3/4	50	SS 1/2-13 x 2-3/4
50	G2 1/2-13 x 3	50	G5 1/2-13 x 3	50	G8 1/2-13 x 3	50	SS 1/2-13 x 3
—	—	25	G5 1/2-13 x 3-1/4	—	—	—	—
25	G2 1/2-13 x 3-1/2	25	G5 1/2-13 x 3-1/2	25	G8 1/2-13 x 3-1/2	25	SS 1/2-13 x 3-1/2
—	—	25	G5 1/2-13 x 3-3/4	—	—	—	—
25	G2 1/2-13 x 4	25	G5 1/2-13 x 4	25	G8 1/2-13 x 4	25	SS 1/2-13 x 4
25	G2 1/2-13 x 4-1/2	25	G5 1/2-13 x 4-1/2	25	G8 1/2-13 x 4-1/2	25	SS 1/2-13 x 4-1/2
25	G2 1/2-13 x 5	25	G5 1/2-13 x 5	25	G8 1/2-13 x 5	25	SS 1/2-13 x 5
25	G2 1/2-13 x 5-1/2	25	G5 1/2-13 x 5-1/2	25	G8 1/2-13 x 5-1/2	25	SS 1/2-13 x 5-1/2
25	G2 1/2-13 x 6	25	G5 1/2-13 x 6	25	G8 1/2-13 x 6	25	SS 1/2-13 x 6
—	—	—	—	25	G8 1/2-13 x 6-1/2	—	—
—	—	25	G5 1/2-13 x 7	—	—	—	—
—	—	25	G5 1/2-13 x 7-1/2	—	—	—	—
25	G2 1/2-13 x 8	25	G5 1/2-13 x 8	—	—	—	—
—	—	—	—	15	G8 1/2-13 x 8-1/2	—	—
25	G2 1/2-13 x 9	—	—	—	—	—	—
—	—	25	G5 1/2-13 x 10	—	—	—	—
25	G2 1/2-13 x 11	—	—	10	G8 1/2-13 x 11	—	—
10	G2 1/2-13 x 14	—	—	—	—	—	—
10	G2 1/2-13 x 18	—	—	—	—	—	—


CONTINUED




Grade 2



Grade 5



Grade 8



Stainless Steel

Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)
----------	---------------------------------	----------	---------------------------------	----------	---------------------------------	----------	---------------------------------

### Hex Head Cap Screws 1/2"-20 - SAE FINE THREAD

—	—	50	G5 1/2-20 x 3/4	—	—	—	—
—	—	50	G5 1/2-20 x 1	50	G8 1/2-20 x 1	—	—
—	—	50	G5 1/2-20 x 1-1/4	50	G8 1/2-20 x 1-1/4	—	—
—	—	50	G5 1/2-20 x 1-1/2	50	G8 1/2-20 x 1-1/2	—	—
—	—	50	G5 1/2-20 x 1-3/4	—	—	—	—
—	—	50	G5 1/2-20 x 2	50	G8 1/2-20 x 2	—	—
—	—	50	G5 1/2-20 x 2-1/2	50	G8 1/2-20 x 2-1/2	—	—
—	—	50	G5 1/2-20 x 3	50	G8 1/2-20 x 3	—	—
—	—	25	G5 1/2-20 x 3-1/2	25	G8 1/2-20 x 3-1/2	—	—
—	—	25	G5 1/2-20 x 4	25	G8 1/2-20 x 4	—	—
—	—	25	G5 1/2-20 x 7	—	—	—	—

### Hex Head Cap Screws 9/16"-12 - USS COARSE THREAD

—	—	25	G5 9/16-12 x 1	—	—	—	—
—	—	25	G5 9/16-12 x 1-1/2	—	—	—	—
—	—	25	G5 9/16-12 x 2	—	—	—	—

### Hex Head Cap Screws 9/16"-18 - SAE FINE THREAD

—	—	25	G5 9/16-18 x 1	—	—	—	—
—	—	25	G5 9/16-18 x 1-1/2	25	G8 9/16-18 x 1-1/2	—	—
—	—	25	G5 9/16-18 x 1-3/4	—	—	—	—
—	—	25	G5 9/16-18 x 2	—	—	—	—
—	—	25	G5 9/16-18 x 2-1/4	—	—	—	—
—	—	25	G5 9/16-18 x 2-1/2	—	—	—	—
—	—	25	G5 9/16-18 x 3	—	—	—	—


### Hex Head Cap Screws 5/8"-11 - USS COARSE THREAD

25	G2 5/8-11 x 1	25	G5 5/8-11 x 1	25	G8 5/8-11 x 1	25	SS 5/8-11 x 1
—	—	25	G5 5/8-11 x 1-1/4	25	G8 5/8-11 x 1-1/4	25	SS 5/8-11 x 1-1/4
25	G2 5/8-11 x 1-1/2	25	G5 5/8-11 x 1-1/2	25	G8 5/8-11 x 1-1/2	25	SS 5/8-11 x 1-1/2
25	G2 5/8-11 x 1-3/4	25	G5 5/8-11 x 1-3/4	25	G8 5/8-11 x 1-3/4	25	SS 5/8-11 x 1-3/4
25	G2 5/8-11 x 2	25	G5 5/8-11 x 2	25	G8 5/8-11 x 2	25	SS 5/8-11 x 2
25	G2 5/8-11 x 2-1/4	25	G5 5/8-11 x 2-1/4	25	G8 5/8-11 x 2-1/4	25	SS 5/8-11 x 2-1/4
25	G2 5/8-11 x 2-1/2	25	G5 5/8-11 x 2-1/2	25	G8 5/8-11 x 2-1/2	25	SS 5/8-11 x 2-1/2
—	—	25	G5 5/8-11 x 2-3/4	25	G8 5/8-11 x 2-3/4	25	SS 5/8-11 x 2-3/4
25	G2 5/8-11 x 3	25	G5 5/8-11 x 3	25	G8 5/8-11 x 3	25	SS 5/8-11 x 3
25	G2 5/8-11 x 3-1/4	—	—	—	—	—	—
25	G2 5/8-11 x 3-1/2	25	G5 5/8-11 x 3-1/2	25	G8 5/8-11 x 3-1/2	25	SS 5/8-11 x 3-1/2
25	G2 5/8-11 x 4	25	G5 5/8-11 x 4	25	G8 5/8-11 x 4	25	SS 5/8-11 x 4
25	G2 5/8-11 x 4-1/2	25	G5 5/8-11 x 4-1/2	25	G8 5/8-11 x 4-1/2	25	SS 5/8-11 x 4-1/2
—	—	25	G5 5/8-11 x 5	25	G8 5/8-11 x 5	25	SS 5/8-11 x 5
25	G2 5/8-11 x 5-1/2	25	G5 5/8-11 x 5-1/2	25	G8 5/8-11 x 5-1/2	25	SS 5/8-11 x 5-1/2
—	—	25	G5 5/8-11 x 6	25	G8 5/8-11 x 6	25	SS 5/8-11 x 6
—	—	25	G5 5/8-11 x 7	—	—	—	—
—	—	25	G5 5/8-11 x 8	—	—	—	—
—	—	—	—	5	G8 5/8-11 x 12	—	—

### Hex Head Cap Screws 5/8"-18 - SAE FINE THREAD

—	—	25	G5 5/8-18 x 1-1/2	25	G8 5/8-18 x 1-1/2	—	—
—	—	25	G5 5/8-18 x 2	25	G8 5/8-18 x 2	—	—
—	—	25	G5 5/8-18 x 2-1/2	25	G8 5/8-18 x 2-1/2	—	—
—	—	25	G5 5/8-18 x 3	—	—	—	—
—	—	25	G5 5/8-18 x 3-1/2	—	—	—	—
—	—	25	G5 5/8-18 x 4	25	G8 5/8-18 x 4	—	—


CONTINUED




Grade 2



Grade 5



Grade 8



Stainless Steel

Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)	Box Qty.	Catalog-No. and Length (Inches)
----------	---------------------------------	----------	---------------------------------	----------	---------------------------------	----------	---------------------------------

### Hex Head Cap Screws 3/4"-10 - USS COARSE THREAD

20	G2 3/4-10 x 1	20	G5 3/4-10 x 1	—	—	—	—
—	—	20	G5 3/4-10 x 1-1/4	—	—	—	—
20	G2 3/4-10 x 1-1/2	20	G5 3/4-10 x 1-1/2	—	—	20	SS 3/4-10 x 1-1/2
20	G2 3/4-10 x 1-3/4	20	G5 3/4-10 x 1-3/4	—	—	20	SS 3/4-10 x 1-3/4
20	G2 3/4-10 x 2	20	G5 3/4-10 x 2	20	G8 3/4-10 x 2	20	SS 3/4-10 x 2
—	—	20	G5 3/4-10 x 2-1/4	—	—	20	SS 3/4-10 x 2-1/4
20	G2 3/4-10 x 2-1/2	20	G5 3/4-10 x 2-1/2	20	G8 3/4-10 x 2-1/2	20	SS 3/4-10 x 2-1/2
—	—	20	G5 3/4-10 x 2-3/4	—	—	—	—
20	G2 3/4-10 x 3	20	G5 3/4-10 x 3	20	G8 3/4-10 x 3	20	SS 3/4-10 x 3
—	—	20	G5 3/4-10 x 3-1/4	—	—	—	—
20	G2 3/4-10 x 3-1/2	20	G5 3/4-10 x 3-1/2	20	G8 3/4-10 x 3-1/2	20	SS 3/4-10 x 3-1/2
20	G2 3/4-10 x 4	20	G5 3/4-10 x 4	20	G8 3/4-10 x 4	20	SS 3/4-10 x 4
20	G2 3/4-10 x 4-1/2	20	G5 3/4-10 x 4-1/2	20	G8 3/4-10 x 4-1/2	20	SS 3/4-10 x 4-1/2
—	—	20	G5 3/4-10 x 5	20	G8 3/4-10 x 5	—	—
—	—	20	G5 3/4-10 x 5-1/2	—	—	20	SS 3/4-10 x 5-1/2
20	G2 3/4-10 x 6	20	G5 3/4-10 x 6	20	G8 3/4-10 x 6	20	SS 3/4-10 x 6
—	—	20	G5 3/4-10 x 6-1/2	—	—	—	—
—	—	20	G5 3/4-10 x 7	—	—	—	—
—	—	20	G5 3/4-10 x 8	—	—	—	—
—	—	—	—	5	G8 3/4-10 x 11	—	—
—	—	—	—	5	G8 3/4-10 x 12	—	—

### Hex Head Cap Screws 3/4"-16 - SAE FINE THREAD

—	—	20	G5 3/4-16 x 1	—	—	—	—
—	—	20	G5 3/4-16 x 2	—	—	—	—
—	—	20	G5 3/4-16 x 2-1/2	20	G8 3/4-16 x 2-1/2	—	—
—	—	20	G5 3/4-16 x 3	20	G8 3/4-16 x 3	—	—
—	—	—	—	20	G8 3/4-16 x 3-1/2	—	—
—	—	20	G5 3/4-16 x 4	—	—	—	—
—	—	20	G5 3/4-16 x 7	—	—	—	—

### Hex Head Cap Screws 7/8"-9 - USS COARSE THREAD

—	—	15	G5 7/8-9 x 2	15	G8 7/8-9 x 2	—	—
—	—	15	G5 7/8-9 x 2-1/2	15	G8 7/8-9 x 2-1/2	—	—
—	—	15	G5 7/8-9 x 3	15	G8 7/8-9 x 3	—	—
—	—	15	G5 7/8-9 x 3-1/2	15	G8 7/8-9 x 3-1/2	—	—
—	—	15	G5 7/8-9 x 4	15	G8 7/8-9 x 4	—	—
—	—	15	G5 7/8-9 x 4-1/2	—	—	—	—
—	—	15	G5 7/8-9 x 5	15	G8 7/8-9 x 5	—	—
—	—	15	G5 7/8-9 x 5-1/2	—	—	—	—
—	—	15	G5 7/8-9 x 6	15	G8 7/8-9 x 6	—	—
—	—	15	G5 7/8-9 x 7	10	G8 7/8-9 x 7	—	—
—	—	15	G5 7/8-9 x 8	—	—	—	—

### Hex Head Cap Screws 1"-8 - USS COARSE THREAD

—	—	—	—	10	G8 1-8 x 2	—	—
—	—	10	G5 1-8 x 2-1/2	10	G8 1-8 x 2-1/2	—	—
—	—	10	G5 1-8 x 3	10	G8 1-8 x 3	—	—
—	—	10	G5 1-8 x 3-1/2	10	G8 1-8 x 3-1/2	—	—
—	—	10	G5 1-8 x 4	10	G8 1-8 x 4	—	—
—	—	10	G5 1-8 x 4-1/2	10	G8 1-8 x 4-1/2	—	—
—	—	10	G5 1-8 x 5	—	—	—	—
—	—	10	G5 1-8 x 6	10	G8 1-8 x 6	—	—
—	—	10	G5 1-8 x 7	—	—	—	—
—	—	—	—	1	G8 1-8 x 10	—	—
—	—	—	—	1	G8 1-8 x 11	—	—
—	—	5	G5 1-8 x 12	—	—	—	—